



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-11-11 Operator Conoco Phillips API #30-0 39-07676
Property Name San Juan 2964H Well No. 22 Location: Unit 12 Section 12 Township 29 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 139 Intermediate 139 Casing 139 Bradenhead 11

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	140	140	27	140
10 min	0	140	140	3	140
15 min	0	140	140	0.7	139
20 min				0	139
25 min				0	139
30 min				0	139

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		✓
Surges		
Down to Nothing	✓	
Nothing		
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 5

REMARKS: BH 1" dead at 10 seconds.
Just Hard blow to lighter at 3 min. a surge at 4.5 min.
Med. Blow at 5 min -

By Jamie Huffman

Witness Monica Kukulany

(Position)

gas & analysis
schematic

E-mail address _____

