



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-1-11 Operator Burlington Res API #30-0 45-07842

Property Name Mangum SRB Well No. 1 Location: Unit Section 29 Township 29 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 7 Intermediate N/A Casing 0 Bradenhead 51

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>7</u>		
10 min	<u>0</u>		<u>7</u>		
15 min	<u>0</u>		<u>7</u>		
20 min	<u>0</u>		<u>7</u>		
25 min	<u>0</u>		<u>7</u>		
30 min	<u>0</u>		<u>7</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>✓</u>	
Nothing	DIST. 3
Gas	OIL CONS. DIV.
Gas & Water	RCVD AUG 1 '11
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 51.1 INTERMEDIATE N/A

REMARKS:

- Slim hole - down to nothing in 1 minute
No flow at 5-10-15-20-25-30

By Che Folbe
MGO COPC
(Position)

Witness Monica Kuehling

E-mail address