



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-4-11 Operator Burlington Res. API #30-0 45-07957
Property Name Grumbling Well No. 3 Location: Unit Section 22 Township 29 Range 9
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 502 Intermediate 0 Casing 572 Bradenhead 344

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	60.2	0	65.7
10 min	0	0	61.2		
15 min	25.6		62		
20 min	1		62.9		
25 min	1		63.7		
30 min	24.3		64.2		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>/ water</u>	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	<u>DIST. 3</u>
Gas & Water	<u>OIL CONS. DIV.</u>
Water	<u>/</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR / FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 29.8

INTERMEDIATE

REMARKS

BH flowing clear water through 1" pipe - 4.73 barrels
water flowed to tank in 30 minutes
Int. Duff to dead in 4 seconds.

By [Signature]

Witness [Signature]

(Position)

E-mail address