



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-17-11 Operator Burlington API #30-0 45-21987

Property Name Howell S Well No. 3A Location: Unit Section 11 Township 30 Range 8

Well Status (Shut-In or Producing) Initial PSI: Tubing 4 Intermediate N/A Casing 26 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>27</u>		
10 min	<u>0</u>		<u>27</u>		
15 min	<u>0</u>		<u>27</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>✓</u>	<u>DIST. 3</u>
Gas	
Gas & Water	<u>OIL CONS. DIV.</u>
Water	<u>RCUD AUG 17 '11</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: Nothing when opened.

By Danny Troy Witness Monica Keeling

(Position)

E-mail address