



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-4-11 Operator Blenington Res API #30-0 45-22778
Property Name El Paso Well No. 1A Location: Unit Section 20 Township 29 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 29.5 Intermediate 1A Casing 131.9 Bradenhead 107.3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>132.3</u>		
10 min	<u>0</u>		<u>132.5</u>		
15 min	<u>0</u>		<u>132.8</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	<u>/</u>
Gas & Water	
Water	
	<u>DIST. 3</u>
	<u>OIL CONS. DIV.</u>
	<u>RCVD AUG 4 '11</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 1A

REMARKS:

dead at 5 seconds

By Justin Amp
(Position)

Witness Monica Kuehling
Questionable

E-mail address