



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-10-11 Operator Burlington API #30-0 45-32059
Property Name Hammer Fed Well No. 1M Location: Unit Section 35 Township 29 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate 258 Casing 263 Bradenhead 642

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	258	264	0	263
10 min	0	258	263	0	263
15 min	0	258	263	0	264
20 min				0	264
25 min				0	263
30 min				0	263

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		/
Surges		
Down to Nothing	/	
Nothing		
Gas		/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 2.5

REMARKS:

BH dead in 6 seconds -
Dr. down to light in 20 seconds - 1 minute - Vapors 5-10-15
-20-25-30 -

By Brian Van Coster

Witness Monica Kullberg

(Position)

E-mail address

