

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 3 1 05 Operator Elm Lung Xisous API #30-0 3921152			
Property Name Duras Campon Well No. Location: Unit O Section 16 Township 24 NR Range 4 W			
Well Status (Shut-In or Producing) Tubing 69 Intermediate Casing 80 Bradenhead 0			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
PRESSURES: TIME BRADENHEAD INTERMEDIATE	CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes 6	80	Steady Flow	
10 minutes <i>Q</i>	80	Surges	
15 minutes 0	80	Down to Nothing	
20 minutes		Nothing X	
25 minutes		Gas	ļ
30 minutes		Gas & Water	
		Water	
If bradenhead flowed water, check all of the descriptions that apply below:			
CLEAR FRESH SALTY SULFUR BLACK ON 11 12 13 74 75			
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE COMPARISONS REMARKS:			
			2729253
By Pul Dus Pumper (Position)		Witness	
E-mail address			