



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-15-04 Operator CDX Rio, LLC API # 3003906003

Property Name Jicarilla Cont. 148-2 Location: Unit I Section 14 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 35 Intermediate _____ Casing 85 Bradenhead ⊖

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH- Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes							
10 minutes							
15 minutes							
20 minutes							
25 minutes							
30 minutes							
5 minute St							

Steady Flow	
Surges	
Down to Nothing	
No Flow	X
Gas	
Gas and Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead ⊖ Intermediate _____

REMARKS:

y James Lopez
T.P.S. Tech
(Position)

Witness _____

NMOCD Test Area:

