



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-21-04 Operator CDX Rio, LLC API # 3003906121

Property Name Jicarilla Cont 147-1 Location: Unit A Section 8 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 174 Intermediate _____ Casing 170 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Flow Descriptions
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	
5 minutes						Steady Flow
10 minutes						Surges
15 minutes						Down to Nothing
20 minutes						No Flow
25 minutes						Gas <u>X</u>
30 minutes						Gas and Water
5 minute St						Water

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:



Witness _____

(Position)

NMOCD Test Area: