



NEW MEXICO DEPARTMENT OF ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-12-04 Operator CDX Rio, LLC API # 3003906153

Property Name Jicarilla Cont 146#12 Location: Unit K Section 4 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 75# Intermediate _____ Casing 65# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Flowed	Flowed
	BH- Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0#</u>					Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing	
20 minutes						No Flow <u>X</u>	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute St						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0# Intermediate _____

REMARKS:

by Nancy Whitson
Tech T.P.S.
(Position)

Witness

Danell Spear T.P.S.

NMOCD Test Area:

