



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-22-04 Operator CDX Rio LLC API # 3003922018

Property Name Jicarilla Cont 147-9 Location: Unit L Section 7 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 180 Intermediate _____ Casing 195 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor
5 minutes	<u>0</u>				
10 minutes					
15 minutes					
20 minutes					
25 minutes					
30 minutes					
5 minute St					


	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing		
No Flow	<u>X</u>	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:



James Simpson
T.P.S. Tech
(Position)

Witness

Harry Whitson T.P.S.

NMOCD Test Area: