



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-13-04 Operator CDX Rio, LLC API # 3003922145

Property Name Jicarilla Cont 146#28 Location: Unit m Section 9 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 110# Intermediate _____ Casing 110# Bradenhead 30#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH.

Time	Bradenhead			Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor
5 minutes	4#	110#			
10 minutes	4#	110#			
15 minutes	5#	110#			
20 minutes	6#	115#			
25 minutes	6#	120#			
30 minutes	5#	120#			
5 minute St	5#	120#			

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing	X 2 min.	
No Flow		
Gas	X	
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 5# Intermediate _____

REMARKS:

by Harry Wilson
Tech T.P.S
(Position)

Witness

Darrell Spear T.P.S

NMOCD Test Area:

