



AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-7-04 Operator CDX Rio, LLC API # 3003923159
Property Name Jiravilla Cont 146 #40 Location: Unit N Section 3 Township 25 Range 5
(Well Name and Number)
Pressure (Shut-in or Producing) Tubing 50# Intermediate _____ Casing 50# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor
5 minutes	<u>0#</u>				
10 minutes					
15 minutes					
20 minutes					
25 minutes					
30 minutes					
5 minute St					

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing		
No Flow <u>X</u>		
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0# Intermediate _____

REMARKS:

y Harry Wilson
Tech T.P.S
(Position)

Witness _____

NMOCD Test Area:

