

AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-19-04 Operator CDX Rio, LLC API # 300398233

Property Name Jicarilla Cont 148#14 Location: Unit C Section 15 Township 25 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) _____ Tubing 0# Intermediate _____ Casing 40# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	<u>0#</u>											
10 minutes												
15 minutes												
20 minutes												
25 minutes												
30 minutes												
5 minute SI												

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0# Intermediate _____

REMARKS:



Harry Whitson
Tech T.P.S.
(Position)

Witness Danell Spear T.P.S.

NMOCD Test Area: