

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

RECEIVED**SEP 02 2011**

Sundry Notices and Reports on Wells

Farmington Field Office
Bureau of Land Management

1. Type of Well
GAS

5. Lease Number
NMSF-078738
6. If Indian, All. or
Tribe Name

2. Name of Operator

ConocoPhillips

7. Unit Agreement Name
San Juan 30-5 Unit

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

8. Well Name & Number
San Juan 30-5 Unit 269

9. API Well No.

30-039-29251

4. Location of Well, Footage, Sec., T, R, M

Unit D (NWNW), 885' FNL & 850' FWL, Section 25, T30N, R5W, NMPM

10. Field and Pool
Basin Fruitland Coal

11. County and State
Rio Arriba, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent

☒ Abandonment

☐ Change of Plans

☐ Other —

☒ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging

☐ Non-Routine Fracturing

☐ Casing Repair

☐ Water Shut off

☐ Altering Casing

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

The subject well was P&A'd on 8/12/2011 per the attached report.

RCVD SEP 6 '11

OIL CONS. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct.

Signed Crystal Tafoya Crystal Tafoya

Title Staff Regulatory Technician Date 9/1/11

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

ACCEPTED FOR RECORD**SEP 06 2011****FARMINGTON FIELD OFFICE****NMOCD**

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979
Farmington, New Mexico 87499
505-325-2627 * fax: 505-325-1211

ConocoPhillips
San Juan 30-5 Unit #269

August 12, 2011
Page 1 of 1

885' FNL & 850' FWL, Section 25, T-30-N, R-5-W
Rio Arriba County, NM
Lease Number: NMSF-078738
API #30-039-29251

Plug and Abandonment Report Notified NMOCD and BLM on 8/9/11

Plug and Abandonment Summary:

- 8/10/11 Road rig and equipment to location. LO/TO equipment on location. RU rig and equipment. Check well pressures: casing 260 PSI, tubing 25 PSI and bradenhead 10 PSI. Blow well down. Pressure test tubing to 1000 PSI. SD for rig repairs. SDFD.
- 8/11/11 Open up well and blow down 115 PSI casing pressure. PU on rods and unseat pump. LD polish rod. TOH and LD rods with top hole down pump. ND wellhead. NU BOP and test. PU tubing and remove donut. TOH and tally 121 joints 2-3/8" tubing, 3728'. Pressure test bradenhead to 400 PSI for 10 minutes. Round trip 7" A-Plus casing scraper to 3537'. SI well. SDFD.
- 8/12/11 Open up well and blow down 110 PSI casing pressure. TIH and set 7" DHS cement retainer at 3537'. Pressure test casing to 800 PSI for 10 minutes.
Plug #1 and #2 combined with CR at 3537', spot 106 sxs Class B cement (125.0 cf) inside casing above CR to 2987' to cover the Fruitland interval and the Kirtland and Ojo Alamo tops.
PUH to 1984'.
Plug #3 spot 30 sxs Class B cement with (35.4 cf) inside casing from 1984' to 1828' to cover the Nacimiento top.
PUH to 193'.
Plug #4 with 50 sxs Class B cement (59.0 cf) from 193' to surface, circulate good cement out casing valve.
TOH and LD tubing with setting tool. SI well. ND BOP. Dig out wellhead. Monitor wellhead. Issue Hot Work Permit. Cut off wellhead. Found cement down 3' in 7" casing and at surface in annulus.
Plug #5 spot 24 sxs Class B cement (28.32 cf) to top off annulus, then install P&A marker. RD and MOL.

Jimmy Morris, MVCI representative, was on location.
Val Jamison, BLM representative, was on location.