



OIL & NATURAL RESOURCES DEPARTMENT

Maralex Resources, Inc
Received

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.d.state.nm.us/ocd/District III3district.htm](http://emnr.d.state.nm.us/ocd/District%20III3district.htm)

2011

Ignacio
Colorado

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 9-28-2011 Operator Maralex Resources API #30-0 H-18
Property Name Brimhall Well No. 2 Location: Unit NE 1/4, NE 1/4 Section 18 Township 30 N Range 11 W
Well Status (Shut-In or Producing) Initial PSI: Tubing 166 Intermediate Casing 4 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		4		
10 min	0		4		
15 min	0		4		
20 min	0		4		
25 min	0		4		
30 min	0		4		

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 6 INTERMEDIATE

REMARKS:

By Pete Tree
Pumper
(Position)

Witness

E-mail address