



NEW MEXICO ENERGY, MINERALS and
NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 10-20-11 Operator Heaven Energy API # 30-0 45-27341

Property Name NEBU Middle Mesa Well # 1 Location Unit Sec 32 Twn 31 Rge 7

Land Type:

State _____
Federal _____
Private _____
Indian _____

Well Type:

Water Injection _____
Salt Water Disposal /
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N) (N) TA Expires: _____

Casing Pres. 0 Tbg. SI Pres. _____ Max Inj. Pres. _____
Bradenhead Pres. 6 Tbg. Inj. Pres. _____
Tubing Pres. 1170
Int. Casing Pres. N/A

Pressured annulus up to 410 psi for 30 mins. Test passed / failed DIST. 3

REMARKS:

fracture put at 7982 OIL CONSV. DIV.
top perf 8064
bottom perf 8899 RCVD OCT 20 '11

By [Signature]
(Operator Representative)

Witness [Signature]
(NMOCD)

(Position)

Revised 02-11-02