



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-9-2011 Operator Manana Gas API #30-0 45-27365

Property Name Marlen S Well No. 41 Location: Unit F Section 27 Township 27N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 125 Intermediate 0 Casing 145 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS		
	Bradenhead		INTERM	BRADENHEAD	INTERMEDIATE	
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0	0	145	0	145	Steady Flow
10 min	↓	↓	↓	↓	↓	Surges
15 min	↓	↓	↓	↓	↓	Down to Nothing
20 min						Nothing <u>Nothing</u>
25 min						Gas
30 min						Gas & Water
						Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

Plunger well, pressure taken with 10 minutes left to off time.

By S. H. Ruiz
Lease Operator
(Position)

Witness _____

E-mail address _____