



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District II/3district.htm](http://emnrd.state.nm.us/ocd/District%20II/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-10-2011 Operator Coleman O. / 8 Gas API #30-0 30-045-32517

Property Name Payne Well No. 2215 Location: Unit J Section 22 Township 32 Range 10

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							<u>N/A</u>
5 min	<u>0</u>	<u>NA</u>	<u>6</u>	<u>NA</u>	<u>NA</u>	Steady Flow	
10 min			<u>6</u>			Surges	
15 min			<u>6</u>			Down to Nothing	
20 min			<u>6</u>			Nothing	<u>✓</u>
25 min			<u>6</u>			Gas	
30 min			<u>6</u>			Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

By Bill Royce

Witness _____

Pumper
(Position)

E-mail address _____