



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emr.state.nm.us/ocd/District III/district.htm](http://emr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-9-2011 Operator Manana Gas API #30-0 45-34312

Property Name Royal Flush Well No. #1 Location: Unit IV Section 22 Township 29N Range 11W


Well Status (Shut-In or Producing) Initial PSI: Tubing 55 Intermediate NA Casing 7 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	NA	7	NA	NA
10 min	0	1	7	1	1
15 min	0	1	7	1	1
20 min	0	1	7	1	1
25 min	0	1	7	1	1
30 min	0	1	7		

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	
Gas & Water	
Water	Clear Water NA



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS.

This is a rod pumped well.
BH dribbled clear water the entire test.
It is so slow you have to splash the level
out of the valve and watch it fill backup.

By [Signature]
Lease Operator
(Position)

Witness _____

E-mail address _____