



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-9-2011 Operator Manana Gas API #30-0 45-34312

Property Name Royal Flush Well No. #1 Location: Unit IV Section 22 Township 29N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 55 Intermediate NA Casing 7 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			FLOW CHARACTERISTICS		
	Bradenhead			BRADENHEAD INTERMEDIATE		
	BH	Int	Csg	Int	Csg	
5 min	0	NA	7	NA	NA	Steady Flow
10 min	0		7			Surges
15 min	0		7			Down to Nothing <u>X</u>
20 min	0		7			Nothing
25 min	0		7			Gas
30 min	0		7			Gas & Water
						Water <u>Clear Water</u> <u>NA</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR X FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS: This is in a rod pumped well.
BH dribbled clear water the entire test.
It is so slow you have to splash the level
out of the valve and watch it fill backup.

By [Signature]
Lease Operator
(Position)

Witness _____

E-mail address _____