



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District 11/3district.htm](http://emnr.state.nm.us/ocd/District%2011/3district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 7-30-10 Operator Enervest Oper LLC API # 30-03922294

Property Name Sicilla 109 Well No. B-1E Location: Unit 1 Section 22 Township 26N Range 5W

Well Status (Shut-In or Producing) Tubing 74 Intermediate NA Casing 98 Bradenhead 90

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>98</u>	Steady Flow	
10 minutes		<u>104</u>	Surges	
15 minutes		<u>110</u>	Down to Nothing <u>15 min</u>	
20 minutes		<u>110</u>	Nothing	
25 minutes		<u>112</u>	Gas <u>✓</u>	
30 minutes		<u>116</u>	Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 15 INTERMEDIATE _____

REMARKS:

Shut in well To Do Test



By Roy Greene

Witness _____

Lezlie Opari
(Position)