## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 4/15/11 Operator			Dugan Production Cor			р	API#	30-045-08524				_			
Property Name	e Garr	ett Fed			_			-					29N	- Range	11W
Well Status(Shut-In or Rroducing) Initial PSI:					Tubing 330 Intermed			li <u>ate_∧</u>	1/A	_Casing _	3	40	Braden	head .	20
OPEN BRA	.DENHE	EAD AN		ΓERN	MEDIATE	TO AT	MOSPH	ERE II	NDIVID	UĄLLY	-OR	15 MINU	TES E	ACH	
	Bradenl	head	Interm						FLOW	CHARAC	TERIS	STICS			
TIME		nt Csg	T	Csg	1			-	BRADE	ENHEAD		INTERME	DIATE	-	
5 mintues	4	340	<del>                                     </del>		s	teady Flo	w							<u>.</u>	
10 minutes	4	340			s	urges								_	
15 minutes	0	340			ם	othing		X							
20 minutes	0	340			N	othing			•					-	
25 minutes	0	340			]	as								<u>.</u>	
30 minutes	0	340	<del> </del>			as & Wa	ter							3456	378970
30 Hilliates	<u></u>		I		1	as & vva /ater	(C)						12	;o``	A
					•	iatoi							(F)	REC	EIVED
If bradent	nead fl	owed	wate	r, ch	eck all	of the	descrip	tions	that a	pply be	<u>elow</u>	<u>:</u>	930	ani.	120111
												ĺ	\83 D	IL CONS	DIV. DIST S
		CLEAR			FRESH_		SALTY		_SULFU	IR	BLAC	<u>K</u>	160		
5 MINUTE SHUT-IN BRADENHEAD								INTER	RMEDIAT	E			18.3	33545	EIVED IZOM DIV. DIST. S
REMARKS:															
					···	<del></del>						<del></del>		-	
												<u> </u>		-	
		<del></del>												-	
		1		<del></del>	<u> </u>	<u>-</u>								-	
Ву	La	Sur_	K)	) eerl			<b></b>	Witne	ss					_	
2			Swite	cher			_								
			(Positi	on)	-										