

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

Date of Test 6/15/11 Operator Dugan Production Corp API # 30-045-20272  
Property Name Moore Well No 1 Location: Unit A Section 7 Township 30N Range 08W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 110 Intermediate 5 Casing 110 Bradenhead 5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	5	5	110	5	110	
10 minutes	5	5	110	5	110	
15 minutes	5	5	110	5	110	
20 minutes	5	5	110	5	110	
25 minutes	5	5	110	5	110	
30 minutes	5	5	110	5	110	

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
X	X

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD

5

INTERMEDIATE

5

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By

Lucy Dunbar

Switcher

(Position)

Witness

