

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC RIM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District W/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 9 MAY 2011 Operator Lively Exp API#30-0 45-21074							
Property Name Lively Well No. 3 Location: Unit N Section 09 Township 3810 Range 860							
Well Status(Shut-In or Producing) Initial PSI: Tubing 128 Intermediate O Casing 277 Bradenhead 29							
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH							
Testing	PRESSURE  Testing Bradenhead INTER  BH Int Csg Int			INTE	RM Csg	FLOW CHAR BRADENHEAD	ACTERISTICS INTERMEDIATE
TIME 5 min_	0	0	257	0	277	Steady Flow	
10 min_	0	0	277	O	277	Surges_	
15 min_	0	0	לכנ		277	Down to Nothing X	
20 min_						Nothing	χ
25 min_						Gas	4920212-
30 min_						Gas & Water	10 to 18 20 21 23 5
						Water	RECEIVED  PUIN 2011  OIL CONS. DIV. DIST. 3
If bradenhead flowed water, check all of the descriptions that apply below:  OIL CONS. DIV. DIST. 3							
•	CLEAR	·	FRESH		SALTY_	SULFUR BLACK	\ <b>3</b>
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE O							
REMARKS:							
By Kissell Donor						Witness	<u> </u>
Position)							
E-mail address							