



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/E/3/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 13 May 2011 Operator Lively Exp API # 30-045-21237

Property Name Lively Well No. 77 Location: Unit E Section 35 Township 3N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 24 Intermediate 17 Casing 27 Bradenhead 34

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	27	0	27
10 min	0	0	27	0	27
15 min	0	0	27	0	27
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

By [Signature]

Witness _____

[Signature]
(Position)

E-mail address _____

