NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

| Date of Test | 10/15/11 | Operator | Dugan Production Co | ro API# | 30-045 | -21318 | | |
|--|--------------------|-------------|---------------------|-------------|-------------------------|-------------|-------------|--------------|
| Property Nam | | | Well No 2 Locatio | | | 18 Township | 30N Range | 10W |
| | | | Tubing NA Interme | | | | | |
| , | | | | | | | | |
| OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH | | | | | | | | |
| PRESSURE Bradenhead Interm FLOW CHARACTERISTICS | | | | | | | | |
| TIME | BH Int Csg Int Csg | | | | BRADENHEAD INTERMEDIATI | | DIATE | |
| 5 mintues | O 12 | p | Steady Flow | | | | | |
| 10 minutes | 0 2 | | Surges | | | | | |
| 15 minutes | 6 12 | 5 | Down to Nothing | | | | | |
| 20 minutes | O 120 | ار | Nothing | | | | | |
| 25 minutes | 0 12 | 0 | Gas | | | | | |
| 30 minutes | O 12 | | Gas & Water | | | | | |
| | | | Water | | | | | |
| 16 lawa at awal | | | | 41 41 4 | | | 238 | 56789707723 |
| If bradenhead flowed water, check all of the descriptions that apply below: | | | | | | | | |
| | CLEA | R | FRESH SALTY | SULFL | JR | BLACK | 303 | CEIVED : |
| | | | | | | ***** | 928 | NC DU DIOT & |
| 5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE | | | | | | | | |
| CLEAR FRESH SALTY SULFUR BLACK 5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE REMARKS: CLEAR FRESH SALTY SULFUR BLACK CONS. DIV. DIST. 3 CONS. DIV. DIST. | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | \bigcap | | | | | | |
| Ву | Like | Spark | | Witness | | | | |
| | 01 | Switcher | | | | | - | |
| | | (Position) | | | | | | • |

