



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://mined.state.nm.us/ocd/District/III3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9 May 2011 Operator Lively Exp API #30-0 45-23974

Property Name Lively Well No. 3E Location: Unit E Section 09 Township 29N Range 8W

Well Status (Shut-In or Producing) Initial PSI: Tubing 121 Intermediate 0 Casing 243 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	243	0	244
10 min	0	0	243	0	244
15 min	0	0	244	0	244
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing			
Nothing	X		X
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_

By Russell Born

Witness \_\_\_\_\_

Russell  
(Position)

E-mail address \_\_\_\_\_

