



**OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3ddistrict.htm](http://emnrd.state.nm.us/ocd/District%20III/3ddistrict.htm)**

(submit 1 copy to above address)

Date of Test 6/13/2011 Operator XTO API #30-045-29122

Property Name W. Cha Cha Unit Well No. 37 Location: Unit Section 27 Township 29 Range 14

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 0 Bradenhead 16

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME	O	NA	O		
5 min	O	NA	O		
10 min	O	NA	O		
15 min	O	NA	O		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	
Gas & Water	
Water	



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

REMARKS: Blew hard for 5 sec then down medium blow, light blow @ 5min,
Pead @ 10min, Air, did not detect gas.

By Larry Baughman
Louse operator
(Position)

Witness

Witness Jane M. D. Kelly

E-mail address

