

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX. (505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 6-30-11 Operator Dugan Production Corp API # 30-045-31263
Property Name State Com Well No 91S Location: Unit J Section 16 Township 32N Range 12W
Well Status(Shut-In or Producing) Initial PSI: Tubing 23 Intermediate 11A Casing 21 Bradenhead 25

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	1	NA	21			
10 minutes	2	NA	21			
15 minutes	3	NA	21			
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 13 INTERMEDIATE _____

REMARKS:

Braden head Blew Down in 13 Sec



By Styler Out
Switcher
(Position)

Witness _____