

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX: (505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3distinc.htm>

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test 6-30-11 Operator Dugan Production Corp API # 30-045-32458
Property Name State Com Well No 2C Location: Unit B Section 16 Township 32N Range 12W
Well Status(Shut-In or Producing) Initial PSI: Tubing 33 Intermediate NA Casing 53 Bradenhead 42

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	1	NA	53			
10 minutes	1.3	NA	53			
15 minutes	1.5	NA	53			
20 minutes						
25 minutes						
30 minutes						

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas	X	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 2 INTERMEDIATE NA

REMARKS:

Bradenhead Blew Down in 30 sec



By HOA
Switcher
(Position)

Witness _____