<u>District I</u> 1625 N. French Dr , Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

Release Notification and Corrective Action													
30-045-06946										al Report	$\boxtimes$	Final Report	
Name of Company: BP						Contact: Jeff Peace							
						Telephone No.: 326-9479  Facility Type: natural gas well API No. 3004506946							
Surface Owner: Federal Mineral Owner: S						State Lease No. NM 012202							
					ATION	OF REI	LEASE						
Unit Letter N	Section 33	Township T28N	Range R8W	Feet from the 790	North/S South	South Line	Feet from the 2200	East/V West	Vest Line	County: San Juan			
<b>Latitude</b> _36.61326 <b>Longitude</b> 107.68757													
NATURE OF RELEASE													
Type of Release: natural gas						Mcf of gas				Recovered: r	o gas r	ecovered	
Source of Release: dump valve on separator						12:00 PM, 9/23/11-9:00 AM, 9/29/11 9/29/11				Hour of Dis	•		
Was Immediate Notice Given?   ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Brandon Powell							
By Whom? Jeff Peace						Date and Hour: 9/30/11 – 9:15 AM							
Was a Watercourse Reached?  ☐ Yes ☒ No						9/29/11  If YES, To Whom? Brandon Powell  Date and Hour: 9/30/11 – 9:15 AM  If YES, Volume Impacting the Watercourses RECEIVED							
If a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.*  The dump valve on the separator was stuck in the open position, releasing gas through the valve into the atmosphere. The well has been shut in and an investigation as to the cause of the failure will be done.													
Describe Cause of Problem and Remedial Action Taken.*  The dump valve on the separator was stuck in the open position, releasing gas through the valve into the atmosphere. The well has been shut in and an investigation as to the cause of the failure will be done.													
Describe Area Affected and Cleanup Action Taken.*  The gas released dissipated into the atmosphere so no clean-up action was possible.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
all Page						OIL CONSERVATION DIVISION							
Signature:  Printed Name: Jeff Peace						Approved by District Supervisor:							
Title: Field Environmental Advisor						Approval Date: 10/11 //   Expirati			Expiration	n Date:			
E-mail Address: peace.jeffrey@bp.com						Conditions of Approval:				Attached			
Date: Se	ptember 30	, 2010	Pl	none: 326-9479									