



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-27-11 Operator Devon Energy API #30-0 39-24236
Property Name YEBUSMS MESA SWB Well No. 1 Location: Unit 10 Township 30 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 278 Intermediate 118 Casing 0 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min					
10 min					
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	☒
Nothing	
Gas	
Gas & Water	
Water	

RCVD OCT 27 '11

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

OIL CONS. DIV.

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0 DIST. 3

REMARKS:

BH Duff when opened
Int blew down in 10 seconds through 1/4" valve.
Leak needs to be closed at this well.

By Phil Jack
LEAF OPERATOR Tech
(Position)

Witness Monica Kuehling

E-mail address _____

Possibly no intermediate
well schematic
Recent Btl-test.