

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	of Test 6-13-2010		Operator —	Energ	Energen Resources		PI# 300	3003924461	
		UNIT FR 101 and Number)	Locatio	Location: Unit K		ownship 32	Range 5		
Pressure (Shut	t-in or Proc	ducing	Tubing _	<u>∐o</u> # Interme	diate _ /	Casing <u></u>	Bradenh	ead	
OPEN I	BRADENHI	EAD AND	INTERMEDIA	TE TO ATMOSF	PHERE INC	DIVIDUALLY FOR 1	I5 MINUTES E	ACH	
	Bradenhead			Intermediate]	B. L. barat		
Tim <u>e</u>	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed Flowed	Intermediate Flowed	
5 minutes	0#	84#	NA	1/4	1/4	Steady Flow			
10 minutes	0	84	1		\ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Surges			
15 minutes		24				Down to Nothing			
20 minutes	0	84				No Flow			
25 minutes	0	84				Gas			
30 minutes	0	84				Gas and Water			
5 minute SI	04	105#			Ą	Water			
<u>lf bradenhea</u>	d flowed w	vater, che	ck all of the d	escriptions tha	t apply bel	ow:			
Clear Fresh Salty Sulfur Black									
5 Minute Shu	u t-in B	radenhead	O#	Intermediat	n/A				
REMARKS:									
									
ву	hael Ha	DW.		Wi	tness				
_Sc	hal Ha Lease	(Position							