Form 3160-5 (February 2005)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

RCVD NOV 29 '11

NOV 22 2011

OMB No. 1004 01375 DIV. Expires: March 31, 2007

| | | | | | l No. | |
|---|--|---|--|--|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS rmington Field | | | | ld ClfficE-078766 | DIST. 3 | |
| Do not use this | s torm tor propo | sals to drill or t | o <u>re</u> renteranand Ma | ana jenikindian, A | llottee or Tribe Name | |
| abandoned well | . Use Form 316 | 0-3 (APD) for su | ch proposals. | | | |
| SUBMIT IN TRIPLICATE – Other instructions on page 2. | | | | 7 If Unit of C | 7 If Unit of CA/Agreement, Name and/or No. | |
| 1. Type of Well | | | | Rosa Unit | | |
| | | | | 8 Well Name | 8 Well Name and No | |
| Oil Well Gas Well Other | | | | 1 | Rosa Unit #260A | |
| 2 Name of Operator | | | | | | |
| Williams Production Company, LLC | | | | 9. API Well N 30-039-295 | | |
| 3a. Address 3b Phone No. (include area code) | | | | | 10. Field and Pool or Exploratory Area | |
| PO Box 640 Aztec, NN | 1 87410 | 505-333-1808 | Basin Fruitland Coal | | | |
| 4. Location of Well (Footage, Sec., T., R, M, or Survey Description) | | | 11. Country or Parish, State | | | |
| SHL 807' FSL & 1969' FEL | | | | | Rio Arrıba, NM | |
| BHL: 2337` FSL & 361` FEL SEC 21 31N 6W | | | | | | |
| 12 CHECK | THE APPROPRIATE | BOX(ES) TO INDIC. | ATE NATURE OF NOTIC | CE, REPORT OR OT | THER DATA | |
| TYPE OF SUBMISSION | | | TYPE OF ACTIO | N | · · · · · · · · · · · · · · · · · · · | |
| | | | | Water Shut-Off | | |
| Notice of Intent | Acidize | Deepen | = | Production (Start/Resume) | | |
| | Alter Casing | Fracture Treat | Reclamation | Reclamation Well Into | | |
| Subsequent Report | Casing Repair | New Construct | ion Recomplet | e | Other COMPLETION | |
| Subsequent Report | Change Plans | Plug and Aban | don 🔲 Temporarı | ly Abandon | | |
| Final Abandon Hent Notice | Convert to Plug Back | | Water Disj | 20001 | | |
| 13 Describe Proposed or Compl | Injection | | | | | |
| all pertinent markers and zor subsequent reports must be recompletion in a new intervequirements, including recl | filed within 30 days fol val, a Form 3160-4 mus amation, have been cor | lowing completion of to the filed once testing l | he involved operations. If the involved operations is the involved operations in the involved operations in the involved operations. | the operation results Abandonment Notice | in a multiple completion or es must be filed only after all | |
| 10/15/11 - RIH and set RBP @ |) 2680'. RDMO loc | ation - | | | | |
| <u>10/16/11-</u> MIRU AWS #222 | | | | | | |
| 10/17/11- Install test plug, pr test good Pull test plug a | | | choke line and TIW valv | ves, 250# low for 5 | min, 1500# for 10 min, all | |
| 14. I hereby certify that the foregoi | ng is true and correct | | | | | |
| Name (Printed/Typed) Heather Riley | | | Title Regulatory Specialist, Sr. | | | |
| f. J | | nue negulatory spec | Jialiot, OL | | | |
| Signature WWW | r Kileer | | Date | | | |
| | THIS SPA | CE FOR FEDER | AL OR STATE OF | FICE USE | | |
| Approved by | | | | | | |
| | | | Title | | Date | |
| Conditions of approval, if any, are attached. Approval of this notice does not warrar certify that the applicant holds legal or equitable title to those rights in the subject le which would entitle the applicant to conduct operations thereon | | | tor | | | |
| | | | | | | |
| Title 18 U.S.C Section 1001 and T | ttle 43 U.S.C. Section 12 | 212, make it a crime for a | ny person knowingly and w | illfully to make to any | department or agency of the | |

(Instructions on page 2)



ACCEPTED FOR RECORD

NOV 2 3 2011

Rosa Unit #260A- Page 2

10/18/11- TOH with RBP @ 2679'. RIH set RBP @ 2676'. Press test 7" casing against blind rams 1600# for 30 min, test pump and charts. All test good.

10/19/11- Mill window from 2659' to 2670'

10/20/11to 10/21/11 - Drill 6-1/4" curve from 2670' to 3555

10/22/11 to 10/24/11 Drill 6-1/4" lateral from 3555' to 5150'. TD 6-1/4" lateral @ 5150' (3224' TVD)

10/24/11- Run 47 Jts 4-1/2", 11.6#, J-55, LT&C, 8rd, perforated casing (28, 0.50" holes p/ft) and 10 jts 11.6#, J-55, LT&C, 8rd, non-perforated casing. CSG set @ 5147' (3224' TVD), TOL @ 2675'. Top perfs @ 3142', bottom perfs @ 5142'. Casing was not cemented.

10/25/11 - RDMO AWS #222

10/31/11- MIRU AWS #471

11/1/11 to 11/15/11 - CO Lateral

11/15/11 - Retreive whipstock

11-16-11 - Retreive RBP @ 2676'

11/17/11 – Land well @ 3239' W /12' KB corr. as follows F/ bottom to top 2 7/8" closed mud anchor @ 3239', 2.28" seat nipple @ 3212' & 101 jts 2 7/8" 6.5# ,j-55,m EUE 8rd tbg,W/ 3-10' subs, 1-6' sub, W/ 200' of cappilary string. RIH F/ bottom to top W/ 2.5"x1 1/4" x 12' RHAC 944 x pump, 4- Norris 1 1/4" sinker bars, 124 norris 3/4" API grade D rods, 8',6' ,4',2' 3/4" subs & 1 1/4"x22' polish rod W/ 1 1/2"x 10' liner