

**NEW MEXICO ENERGY, MINERALS
DISTRICT OFFICE
& NATURAL RESOURCES DEPARTMENT**

OIL CONSERVATION DIVISION AZTEC

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

Date of Test 7/27/2011 Operator Burlington Resources API # 3003923501
Property Name SAN JUAN 30-6 UNIT Well No. 112Y Location: Unit A Section 26 Townshi 030N Range 006W
Well Status Flowing Initial PSI: Tubing 290 Intermediat 0 Casing 372 Bradenhea 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				FLOW CHARACTERISTICS	
	BRADENHEAD		INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg	
5 min		0	372		372	Steady Flow
10 min		0	372		372	Surges
15 min		0	372		372	Down to Nothing Y
20 min		0	372		372	Nothing Y
25 min						Gas Y
30 min						Gas && Water
						Water

If Bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

If Intermediate flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE Bradenhead 0 Intermediate 0

REMARKS:

BH blew down in 2 min thru 2" valve.

RCVD NOV 22 '11

OIL CONS. DIV.

Tested By aguirdh

Witness No

DIST. 3