

Oct 6 , 2011

Energen Resources
2010 Afton Place
Farmington , NM 87401

This letter is to certify that D & D Services LLC did run deviation surveys at the below listed depths on your Richardson # 103 in San Juan County

Richardson # 103 Sec 1 T 27N R 13 W

165' $\frac{1}{2}$


665' $\frac{3}{4}$

1165' 1 $\frac{1}{4}$

1525' 1 $\frac{1}{4}$

To the best of my knowledge, I swear this information to be true.

Sincerely,



Glen Davis
Drilling Manager

RCVD NOV 29 '11

OIL CONS. DIV.
DIST. 3



AV