

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources'

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-09128

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP America Production Co.	Contact: Courtney Cochran
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457
Facility Name: Florance K 29	Facility Type: natural gas well API # 300450912800

Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF 078385
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter K	Section 25	Township 30N	Range 08W	Feet from the 1500	North/South Line South	Feet from the 3730	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.77999 Longitude 107.63084

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 254 MCF	Volume Recovered: none
Source of Release: dump valve on interstage scrubber	Date and Hour of Occurrence: 6/6/2011 - 6/8/2011	Date and Hour of Discovery: 10 00 am on 6/8/2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Technician arrived on location to start compressor and found hung dump valve on interstage scrubber. Adjustments made to controller and well was put back on line.

Describe Area Affected and Cleanup Action Taken.*

Natural Gas dissipated to the atmosphere, so no clean action was possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.



Signature: <i>C. Cochran</i>		OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran		Approved by District Supervisor: <i>Jonathan D. Kelly</i>	
Title: Environmental Challenger		Approval Date: 12/05/2011 Expiration Date:	
E-mail Address: Courtney.Cochran@bp.com		Conditions of Approval:	
Date: 06/15/2011 Phone: 505-326-9457		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

nJK1133947817