

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-23989

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BP	Contact: Courtney Cochran
Address: 200 Energy Court, Farmington, NM 87401	Telephone No.: 326-9457
Facility Name: Johnson Com B 002-PC	Facility Type: natural gas well API # 300452398900

Surface Owner: Federal	Mineral Owner: Federal	Lease No. 04202
------------------------	------------------------	-----------------

LOCATION OF RELEASE

Unit Letter P	Section 11	Township T28N	Range R9W	Feet from the 790	North/South Line South	Feet from the 930	East/West Line East	County: San Juan
------------------	---------------	------------------	--------------	----------------------	---------------------------	----------------------	------------------------	---------------------

Latitude 36.6715 Longitude 107.75223

NATURE OF RELEASE



Type of Release: natural gas	Volume of Release: approx. 110 Mcf of gas	Volume Recovered: no gas recovered
Source of Release: site glass	Date and Hour of Occurrence: 10:00 a.m. on 1/11/2011 - 12:00 p.m. on 1/12/2011	Date and Hour of Discovery: 1/12/2011
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Broken site glass on the suction scrubber of the compressor allowed gas to escape. Well was coded, compressor isolated and mechanic called. Repair has been made and unit restarted.

Describe Area Affected and Cleanup Action Taken.*
The gas released dissipated into the atmosphere so no clean-up action was possible.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by District Supervisor: 	
Title: Environmental Challenger	Approval Date: 12/05/2011	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: January 14, 2011	Phone: 326-9457	

* Attach Additional Sheets If Necessary



nJK 1133949037