District J
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action											
						ERATOR				Report	
Name of Co	ompany	ConocoPhi	illips Cor	npany		Contact Kelsi Harrington					
Address 3401 E. 30 <sup>th</sup> St., Farmington, NM 87402						Telephone No. 505-599-3403					
Facility Name FC State Com 4A						Facility Type	•	Gas Well API#3004532161			
Surface Owner State Mineral Owner						State		Lease No. <b>E 284-21</b>			
LOCATION OF RELEASE											
Unit Letter					No	th/South Line   Feet from the   East/West Line   County					
С	36	3 <u>1N</u>	09W	1255'		North	1530'	West		San Jua	ın
Latitude <u>36.85816° N</u> Longitude <u>-107.73542° W</u>											
NATURE OF RELEASE											
		duced Wate				Volume of Release – 240 BBL			Volume Recovered – 240 BBL		
Source of Re	elease: Inje	ection Pum	р			Date and Hour of Occurrence			Date and Hour of Discovery		
Was Immediate Notice Given?						Unknown         1/4/2011         12:45 p.m.           If YES, To Whom?         1/4/2011         12:45 p.m.					<u>n.</u>
Was immediate Notice Given?  ✓ Yes ☐ No ☐ Not Required						Brandon Powell (NMOCD): Verbal					
By Whom? Kelsi Harrington						Date and Hour – 1/5/2011 2:20 p.m.					
Was a Watercourse Reached?  ☐ Yes ☒ No						If YES, Volur	ne Impacting the	Watercourse.			_
If a Watercourse was Impacted, Describe Fully.*											
Describe Cause of Problem and Remedial Action Taken.* Freezing temperatures caused a check valve at the water transfer pump to freeze and rupture. Upon discovery, the leak was isolated and a water truck was called to location.											
Describe Area Affected and Cleanup Action Taken.* All fluid remained within the berm and approximately 240 BBL of fluid were											
recovered. ConocoPhillips will assess the soil to determine if further action will be needed.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and											
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability											
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other											
federal, state, or local laws and/or regulations.											
Signature: Kelon Harrington						OIL CONSERVATION DIVISION					
Printed Name: Kelsi Harrington						Approved by District Supervisor:					
Title:	En	vironmenta	ıl Consul	tant		Approval Date: 12/65/201/ Expiration Date:					
E-mail Add	ress: <b>kelsi.</b>	g.harringto	on@conc	cophillips.cor	n	Conditions of	Approval:	, ,		Attached	

\* Attach Additional Sheets If Necessary

Phone: 505-599-3403



NJK 1133950710