

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-32975

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	ConocoPhillips Company	Contact	Kelsi Harrington
Address	3401 E. 30 th St., Farmington, NM 87402	Telephone No.	505-599-3403
Facility Name	San Juan 32-7 Unit 220A	Facility Type	Gas Well
		API #	3004532975
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	SF-078996

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	31	32N	07W	680'	South	268'	West	San Juan

Latitude 36.93422° N Longitude -107.61691° W

NATURE OF RELEASE

Type of Release – Produced Water	Volume of Release – 123 BBL	Volume Recovered – 0 BBL
Source of Release: Transfer Pump	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 1/9/2011 10:30 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell (NMOCD): Verbal and E-mail Sherrie Landon (BLM): Verbal and E-mail	
By Whom? Kelsi Harrington	Date and Hour – 11/10/2011 10:55a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		

Describe Cause of Problem and Remedial Action Taken.* The 3" suction hose coming from the transfer pump to the water tank disconnected causing produced water to be released from the tank. Upon discovery, the suction valve was closed on the tank.

Describe Area Affected and Cleanup Action Taken.* All fluid remained in the berm however no fluid was recovered. ConocoPhillips Company will assess the soil to determine if further action will be needed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Kelsi Harrington	OIL CONSERVATION DIVISION	
Printed Name: Kelsi Harrington	Approved by District Supervisor: [Signature]	
Title: Environmental Consultant	Approval Date: 1/26/2011	Expiration Date:
E-mail Address: kelsi.g.harrington@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/18/11 Phone: 505-599-3403		

* Attach Additional Sheets If Necessary

nJK 1133949619

