



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-27-2011 Operator Kukui Operating API #30-0 45-28438
Property Name Hardie Well No 2517 Location: Unit L Section 25 Township 29N Range 8W
Well Status (Shut-In or Producing) Initial PSI: Tubing 115 Intermediate NA Casing 115 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			FLOW CHARACTERISTICS	
	Bradenhead		INTERM	BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
5 min	<u>0</u>	<u>NA</u>	<u>115</u>		
10 min	<u>↓</u>	<u>↓</u>	<u>↓</u>		
15 min	<u>↓</u>	<u>↓</u>	<u>↓</u>		
20 min	<u>↓</u>	<u>↓</u>	<u>↓</u>		
25 min	<u>↓</u>	<u>↓</u>	<u>↓</u>		
30 min					

Steady Flow	
Surges	
Down to Nothing	
<u>Nothing</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE _____ BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

This is a flowing well with the casing and tubing equalized. I performed this test one day late because of bad mud

By [Signature] Witness _____
Lease Operator
(Position)

E-mail address _____

RCVD NOV 14'11

OIL CONS. DIV.

DIST. 3