RECEIVED

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NOV 3 0 2011

Sundry Notices and Reports on Wells Farmington Field Bureau of Land Man		armington Field Office rau of Land Managemen
	5.	Lease Number NM-03863
. Type of Well GAS	6.	If Indian, All. or Tribe Name
. Name of Operator	7.	Unit Agreement Name
BURLINGTON		
RESOURCES OIL & GAS COMPANY LP	0	W.H.M O M
Address & Phone No. of Operator	— 8.	Well Name & Number VALDEZ 8C
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API Well No.
		30-039-30362
Location of Well, Footage, Sec., T, R, M	10.	Field and Pool
Surface: Unit A (NENE), 1350' FNL & 1120' FEL, Section 28, T28N, R4W, NMPM		Blanco MV/Basin DK
BH: Unit G (SWNE), 1410' FNL & 1860' FEL, Section 28, T28N, R4W, NMPM	11.	County and State Rio Arriba, NM
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT,	OTHER	DATA
Type of Submission Type of Action Notice of Intent Abandonment Change of Plans	Х	
Recompletion New Construction		RCVD DEC 6'11
Casing Repair Water Shut off		OIL CONS. DIV.
Final Abandonment Altering Casing Conversion to Injection		DIST. 3
13. Describe Proposed or Completed Operations		
14. PLEASE SEE ATTACHED		
PT will be conducted by Completion Rig. Results & TOC will appear on next report.		
4. I hereby certify that the foregoing is true and correct.		
Signed Denise Journey Title: Regulator	y Technic	<u>cian</u> Date <u>11/29/11</u>
This space for Federal or State Office use)		_
APPROVED BYTitleTitle		_ Date
OUTDITION OF BUILDOAND, ILUMY.		

ACCEPTED FOR RECORD

NMOCD

DEC 0 1 2011



VALDEZ 8C BURLINGTON RESOURCES API# 30-039-30362 Blanco Mesa Verde/Basin Dakota

10/13/11 10/14/11	MIRU AWS 711. NU BOPE. PT 9 5/8" csg to 600#/30 min. Test QK. TIH w/ 8 3/4" bit, tag cmt @ 196' & DO. Drilled ahead to 4,695' Inter. TD reached
10/1-7/11	10/17/11.
10/18/11	Circ. hole. TIH w/ 108 jts., 7", 23#, J-55, LT&C csg., set @ 4,685' w/
	Stage tool @ 3,900'.
10/19/11	RU to cement. 1st Stage: Pre-flush w/ 10 bbls GW & 2 bbls FW. Pumped
	scavenger 19 sx (57cf-10bbls=3.02 yld) Premium Lite cmt w/ 0.3% CACL, .25 pps cello-flake, 5 pps LCM-1, 0.4% FL-52, 8% bentonite, & 0.4% SMS.
	Lead w/ 19 sx (40cf-7bbls=2.13 yld) Premium Lite cmt w/ 0.3% CACL,
	.25 pps cello-flake, 5 pps LCM-1, 0.4% FL-52, 8% bentonite, & 0.4% SMS.
	Tail w/ 85 sx (117cf-21bbls=1.38 yld) Type III cmt., w/ 1% CACL, .25 pps
	Cello-flake, & 0.2% FL-52. Drop plug and displaced w/ 40 bbls FW. Bump plug
	& open stage tool @ 3,900'. Circ 12 bbls cmt to surface. Plug down @
	07:08 hrs on 10/19/11. WOC.
	2 nd Stage: Pre-flush w/ 10 bbls FW, 10 bbls GW, & 10 bbls FW. Pumped scavenger 19 sx (57cf-10bbls=3.02 yld) Premium Lite w/ 0.3% CACL, .25 pps
	cello-flake, 5 pps LCM-1. 0.4% FL-52, 8% bentonite, & 0.4% SMS. Lead w/ 491
	sx (1045cf-186bbls=2.13 yld) Premium Lite w/ 0.3% CACL, .25 pps cello-flake, 5
	pps LCM-1, 0.4% FL-52, 8% bentonite, & 0.4% SMS. Drop plug and displaced
	w/ 154 bbls FW. Bump plug & close stage tool. Circ. 45 bbls cmt to surface.
	Plug down @ 12:55 hrs on 10/19/11. RD cmt. WOC.
10/20/11	TIH w/ 6 1/4" bit. PT 7" csg. to 1500#/30 min. Test OK. DO cmt & stage tool @
10/27/11	3,900'. Drilled ahead to 8500' on 10/26/11. Drill pipe became stuck. Notified Forest Service, Mark Catron, requesting a time extension into
10/2//11	winter closure, due to drill pipe being stuck in hole. Approval received for
	extention to 11/14/11.
	Notified Agencies - Jim Lovato (BLM) & Charlie Perrin (OCD) requesting
	permission to back off drill pipe @ 6,568' and jar free. Approval received
10100111	10/27/11.
10/28/11	Notified Agencies - Wayne Townsend (BLM) & Charlie Perrin (OCD). Jarring unsuccessful to free pipe. Requesting permission to perf @ 8,310'
	to attempt to circulate & perf @ 6,618' if unsuccessful @ 8,310'. Approval
	received 10/28/11.
10/28/11	TIH to perf @ 8,100' w/ 4 SPF. Unable to pump through perfs. Shot 4SPF @
	6,700'. Unable to pump through perfs. RD WL.
10/29/11	Notified Agencies – Wayne Townsend (BLM) & Charlie Perrin (OCD),
	requesting permission to sidetrack (perfs were unsuccessful) as follows: Set cmt retainer @ 4,638'. Pump 138 bbls Premium Lite cmt. Set whipstock
	on top of cmt. retainer & mill window. Approval received 10/29/11.
10/29/11	TIH w/ cement retainer, set @ 4,636'. PT csg & retainer @ 510#/10 min Test
	OK. Establish injection rate & pumped 389 sx (774cf-138bbls=1.99 yld) -lost 10
	bbls cmt due to cmt truck valve coming loose = 128bbl pumped, Premium Lite
	HS cmt w/ 0.3% CACL2, .25 pps cello-flake, 0.4% FL-52, 5 pps LCM-1, 0.4%
	SMS, & 8% bentonite. Displaced w/ 50 bbls FW, Sting out of retainer @ 20:45 hrs on 10/29/11. RD cmt. WOC.
10/30/11	Notified Agencies, Wayne Townsend (BLM) & Charlie Perrin (OCD), only
	pumped 128 bbls cmt instead of 138 bbls. Cement truck had a valve come
	loose and lost 10 bbls cmt. Cement is up to CR. Approval received
	10/30/11.

VALDEZ 8CBURLINGTON RESOURCES
API# 30-039-30362

Blanco-Mesa-Verde/Basin-Dakota-

10/30/11 TIH w/ whipstock, work through Stage Tool @ 3,900'. Set whipstock @ 4,622'. Mill window in casing – top of window @ 4,623', btm @ 4,630'.

TIH w/ 6 ½" bit, drill sidetrack hole from 4,630' to 5,118' w/ mud.

11/4/11 TIH w/ 6 ½" bit, drilled ahead.

11/14/11 Notified Forest Service, John Reidinger, requesting a time extension into

winter closure, due to problems on the well. Approval received for

extention to 12/1/11.

11/20/11 Reached TD of **8,845**' on 11/20/11.

11/21/11 TIH w/ 207 jts., (168 jts. LT&C and 38 jts., BT&C) 4 ½" 11.6#, L-80 csg., set @

8.833'.

11/22/11 RU to cmt. Pre-flush w/ 10 bbls FW, 10 bbls GW, & 10 bbls FW. Pumped

scavenger 9 sx (27cf-5bbls=3.02 yld) Premium Lite w/ 0.3% CD-32, .25 pps cello-flake, 1% FL-52, & 6.25 pps LCM-1. **Tail** w/ 283 sx (560cf-100bbls=1.98 yld) Premium Lite w/ 0.3% CD-32, .25 pps cello-flake, 1% Fl-52, & 6.25 pps LCM-1. Drop plug and displaced w/ 137 bbls FW (1st 10 bbls w/ sugar). Bump plug. Plug down @ 13:20 hrs on 11/22/11. RD cmt. WOC. ND BOPE. NU WH.

RD RR @ 10:00 hrs on 11/23/11.