



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District III/3district.htm](http://emmr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD DEC 19 '11

OIL CONS. DIV.

DIST. 3

Date of Test 12-19-11 Operator Burlington Res. API #30-0 45-29936

Property Name Vasaly Com Well No. 2 Location: Unit Section 22 Township 30 Range 4

Well Status (Shut-In or Producing) Initial PSI: Tubing 1049 Intermediate 0 Casing 820 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	1049	0	22
10 min	0	0	1049	0	22
15 min	0	0	1049	0	23
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	/
Nothing		
Gas		/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH Puff when opened.
Int. to nothing in 30 seconds.

By Randy Nelson
(Position)

Witness Monica Kuehling

E-mail address