NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-1-11 Operator Burlington Res API #30-0 45 07809

Property Name Mangum Well No. 4 Location: Unit ___ Section 28 Township 29 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 324 Intermediate N/A Casing 315 Bradenhead 18

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE Bradenhead BH	Int	Csg	INTERM Int	Csg
TIME 5 min	0		306		
10 min	0		304		
15 min	0		302		
20 min	0		298		
25 min	0		295		
30 min	0		292		

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow	✓	
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water	✓	

DIST. 3
OIL CONS. DIV.
RCVD AUG 1 '11

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 44 INTERMEDIATE N/A

REMARKS: 9-6- rig on lst. filled with Dand 1.5" Start 2.5 = 65 gallons
dead at 4 minutes Started flowing water at 25 min.
Casing dropped while BH open. Failure

By Che Rolne Witness Monica Kuehling

MSO Cofc
(Position)

E-mail address _____