



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-22-11 Operator Burlington Res API #30-0 45-09248
Property Name Riddle B Well No. 1 Location: Unit Section 27 Township 30 Range 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 80 Intermediate 240 Casing 230 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min				200	203
10 min				185	190
15 min				160	182
20 min				170	180
25 min				165	164
30 min				154	156

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	/
Surges	
Down to Nothing	/
Nothing	
Gas	/
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 160

RCVD JUL 22 '11

OIL CONS. DIV.

DIST. 3

REMARKS:

BH - puff when opened.
Int. blew whole 30 minutes dropping with casing

By Alicia Montoya
M50-COP
(Position)

Witness Monica Luchang

E-mail address