



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/10/2011 Operator ConocoPhillip API #30-045-30171

Property Name Federal Well No. 10B Location: Unit 1 Section 1 Township 29 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 85 Intermediate NA Casing 90 Bradenhead 526

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	24↑		94		
10 min	5↑		96		
15 min	2.5↑		97		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	✓
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD ☐ INTERMEDIATE ☐

REMARKS:

Extremely hard blow for 2 1/2 min, hard blow for 1 min, moderate blow 3 min, -
Diagram indicates it should have intermediate, but only one head showing
- figure the BH is still barried and we were testing intermediate - Reschedule

By _____

Witness _____

(Position)

E-mail address _____

