



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-6-11 Operator Burlington Res API #30-0 45-22437
Property Name Burlington Well No. 1A Location: Unit Section 25 Township 31 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 174 Intermediate 0 Casing 176 Bradenhead 14

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead Int	Csg	INTERM Int	Csg
TIME					
5 min	<u>0</u>		<u>198</u>		
10 min	<u>0</u>		<u>176</u>		
15 min	<u>0</u>		<u>177</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>/</u>
Nothing	
Gas	<u>DIST. 3</u>
Gas & Water	
Water	<u>OIL CONS. DIV.</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

RCVD SEP 6 '11

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 7 INTERMEDIATE

REMARKS: Paft when opened
Re-test in 6 months

By [Signature] Witness Monica Kuehling
Area 4 Production Engineer
(Position)

E-mail address

Well Name: Bruington #1a

Date: 8-10-11

Tubing hanger seals would not
test

Casing hanger seals test GOOD
2000psi for 10min.

ConocoPhillips

**BURLINGTON
RESOURCES**


ConocoPhillips **BRUINGTON 1A
FORMATION MV**

**LATITUDE N 36° 52.3
LONGITUDE W 107° 56.8**

**1450' FNL 1025' FWL
SEC. 25 T031N R011W
LEASE NO. FEE ELEV. 5757
API NO. 30-045-22437
SAN JUAN COUNTY, NEW MEXICO
EMERGENCY CONTACT 1-800-592-4822**

Well Name: Bruington #1a

Date: 8-10-11



ConocoPhillips