



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-15-11 Operator DS Simmons Inc API #30-0 45-07939

Property Name LV Hammer Well No. A1 Location: Unit Section 21 Township 29N Range 9W

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 13 Intermediate 0 Casing 13 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>0</u>	<u>13</u>	<u>0</u>	<u>13</u>
10 min	<u>0</u>	<u>0</u>	<u>13</u>	<u>0</u>	<u>13</u>
15 min	<u>0</u>	<u>0</u>	<u>13</u>	<u>0</u>	<u>13</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	<u>X</u>
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

By Scott Elmen
Field Tech.
(Position)

Witness

E-mail address

