NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division

Aztec District Office

1000 Rio Brazos Road

Aztec, NM 87410

(505)334-6178 FAX:(505)334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(Submit 1 copy to above address)

Date of Test	ite of Test <u>UIS/II</u> Operator			Dugan	Produ	ction Cor	р	_API#	30-045	5-084	.99				
Property Name	∍ Ju	lander (Gas C	om	Well No_	1	Location:	Unit	J	Section	10	Township	29N	Range	11W
Well Status(Shut-In or Producing) Initial PSI:					Tubing _	Fubing 300 Intermediate N/A				Casing	Ĺ	100	Bradenl	nead	145
						-			,						
OPEN BRA	DEN+	HEAD AI	ND IN	TERN	//EDIATI	E TO A	ГМОЅРН	ERE IN	NDIVID	UALLY	FOR	15 MINU	TES E	ACH	
		PRESS													
	Bradenhead Interm				FLOW CHARACTERISTICS										
TIME	BH 2	Int Csg	11	Csg	1			-	BRADI	ENHEAD		INTERME	DIATE		
5 mintues	-			<u> </u>	;	ow									
10 minutes	3	57 ⁰			:	Surges									
15 minutes	3	392			ļ	Down to N	Nothing								
20 minutes	3	390] ,	Nothing									
25 minutes	4	390] ,	Gas			X			-			
30 minutes	4	390			1 ,	Gas & Wa	ater		-/					•	
				Water						•					
													123	,456 Z	789707
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK															
												33		CE	VED
		CLEAF			FRESH_		_ SALTY		_SULFL	JR	BLAC	K \N	30 0	00:0 00:0	197
5 MINUTE	сынт	'_INI	DDAI	SENILE	:AD	25	_	INTER	MEDIAT	·e		/2	.0. 	ons on	DIST 9
SALTY SULFUR BLACK OF MICONS ONE OF SECRET														-0761°3	
													,,	2223	160
											-			•	
														-	
		<u> </u>												-	
												·		-	
	<i></i>			1											
By July Allich							Witnes	ss			· .		-		
			Swi ¹ (Posi	tcher											